

Text in *green* is to be part of UCSF building database and may be part of UCOP database.

Date: 2020-11-03


## UCSF Building Seismic Ratings

### Millberry Garage, Parnassus Avenue


CAAN# 2212.1

500 Parnassus Avenue, San Francisco, CA 94131

UCSF Campus Site: *Parnassus*



11/03/2020



Rating summary	Entry	Notes
UC Seismic Performance Level (rating)	V	Findings based on a drawing review and ASCE 41-17 Tier 1 & 3 evaluation <sup>1</sup>
Rating basis	Tier 1 & 3	ASCE 41-17
Date of rating	2020	
Recommended UCSF priority category for retrofit	Priority B	Priority A=Retrofit ASAP Priority B=Retrofit at next permit application for modification
Ballpark total project cost to retrofit to IV rating	Very High (> \$400/sf)	See recommendations on further evaluation and retrofit
Is 2018-2019 rating required by UCOP?	Yes	Building previously rated IV but does not have a fully documented quantifiable review
Further evaluation recommended?	Yes	Additional analysis to determine size and scope of required retrofit

<sup>1</sup> The evaluations at UCSF translate the Tier 1 & 3 evaluation to a Seismic Performance Level rating using professional judgment discussed among the Seismic Review Committee. Non-compliant items in the Tier 1 & 3 evaluation do not automatically put a building into a particular rating category, but such items are evaluated along with the combination of building features and potential deficiencies, focused on the potential for collapse or serious damage to the gravity supporting structure that may threaten occupant safety.

**Building information used in this evaluation**

- “Combined Structure – Unit No. 1 (Quarter of nurses, interns, and resident staff; student union, including physical education and recreation facilities; and parking garage)” structural drawings, Milton T. Pflueger (Architect) and Huber & Knapik (Civil Engineers), dated 14 July 1955.
- “Combined Structure – Unit No. 2” structural drawings, Milton T. Pflueger (Architect) and Huber & Knapik (Civil Engineers), dated 21 May 1958.
- *Performance of UCSF Buildings During the October 17, 1989 Loma Prieta Earthquake*, Impell Corporation, dated 17 November 1989.

**Scope for completing this form**

Reviewed original structural construction drawings and performed an ASCE 41-17 Tier 1 & Tier 3 evaluation. Made a brief site visit of building exterior and walked through parking garage levels. Did not observe nonstructural life-safety hazards within or outside of the building.

**Brief description of structure**

The building comprises about half of the 400,000 sq ft Millberry combined structure. The structure was constructed in phases described as Units No. 1, 2, and 3 in the original structural drawings.

- Units No. 1 and No. 3 encompass the student union building located south of the Garage. The main building is five stories (Level C to Level 2). A tower on the west side of the building extends up three additional stories while the tower on the east side extends up four additional stories. The top two levels of the east tower (Level 5 and Roof) were constructed as the later Unit No. 3. The remainder of the Union building was included in the original Unit No. 1 construction.
- Unit No. 2 is the seven-story (Level H to Level A) parking garage with circular ramps located on the east and west ends.

The focus of this report is the Millberry Garage building (Unit No. 2). The garage was designed in 1958 and constructed shortly thereafter.

There is no joint between the Garage and Union buildings. The Garage’s slab reinforcing was welded to existing dowels extended from the Union’s slabs at Levels A and B. Additionally, during the Garage’s construction, a shared retaining wall was constructed from Level E to Level C and keyed into the existing Union’s caisson foundations.

Identification of Levels: The building is sited on a severe slope. The levels are identified in the structural drawings as follows:

- Level H: EL. 307.52 ft – aligned with grade at Irving Street along the north side of the building
- Level G: EL. 316.58 ft
- Level F: EL. 325.23 ft
- Level E: EL. 334.08 ft
- Level D: EL. 342.94 ft
- Level C: EL. 351.79 ft
- Level B: EL. 360.65 ft
- Level A: EL. 369.50 ft

The Garage Levels C through A are roughly aligned with the adjacent Union Levels C through A.

Grade at the north side of the structure along Irving Street is at approximately EL. 307 ft, roughly aligned with the Garage Level H. Grade at the south side of the structure along Parnassus Avenue is at approximately EL. 393 ft, roughly aligned with the Union Level 1, two stories above the top of the garage.

Foundation System: The parking garage foundations comprise reinforced concrete spread footings below columns and reinforced concrete strip footings below walls. The southernmost columns along Line P are founded on belled caissons.

Structural System for Vertical (Gravity) Load: The parking garage floor framing comprises a 12 in. deep two-way flat slab with drop panels, supported by reinforced concrete columns spaced such that bay sizes are 34 ft x 32 ft. The slab drop panels are 20 ft x 20 ft in plan tapering from 24 in. thick at the columns to 12 in. thick at their perimeter. The drop panels are typically unreinforced. Typical interior columns are cylindrical with diameters ranging from 24 in. to 36 in. with spiral confinement steel surrounding the vertical steel reinforcement. Spiral reinforcement ranges from 3/8 in. dia. to 1/2 in. dia. with a pitch ranging between 2 in. and 3-1/4 in. The lower story columns have two concentric spiral cores around an inner and outer ring of vertical reinforcing creating double confined cores. Columns located along the north building elevation are rectangular with #4 hoops and #3 cross-ties engaging all vertical bars. Hooks and ties are detailed with both 135-degree or 180-degree hooks. Hoop and tie spacing is identified as 3 in. at the top and bottom 14 in. of the columns with the balance of hoops and ties spaced at 12 in. o.c. The garage has two helical ramps comprising an 8 in. thick reinforced concrete slab driveway, located at each end of the building. These helical ramps are supported by curved concrete walls on each side of the ramp slab. The interior ramp wall is a 16 in. solid wall; the exterior wall is a 16 in. punched wall with regularly-spaced openings.

Structural System for Lateral Loads: The garage does not have a clearly defined lateral load-resisting system as walls, columns, beams and slabs all significantly contribute to the building's lateral load resistance. The reinforced beams (at the north perimeter), reinforced flat slab (at the interior) and columns will resist load through frame action. Reinforced concrete retaining walls at the south side of the building and the curved ramp walls at the east and west ends provide much of the structure's stiffness. However, the efficacy of the wall system is limited by the strength of the diaphragms.

#### **Brief description of supplemental analysis model**

A linear response spectrum analysis model was developed in accordance with ASCE 41-17 procedures to determine the anticipated building response when subject to seismic loads. The model includes an increased seismic demand associated with the retained soil south of the building in the form of an earth pressure seismic increment. This model was used to identify potential areas of overstress under the BSE-R hazard with a Life Safety performance objective and under the BSE-C hazard with a Collapse Prevention performance objective. Concrete shear walls, beam-column moment frames, and slab-column moment frames were all considered as primary lateral force-resisting components.

#### **Brief description of seismic deficiencies and expected seismic performance**

Seismic deficiencies that affect the building performance include:

- Garage concrete column axial stresses, caused by overturning forces alone, exceed 0.3 f'c.
- Garage moment frames comprise flat slab frames. The drop panels in the concrete slabs are not adequately reinforced, thereby adding no increase to the flexural capacity of the slab.

- Garage flat slab and spandrel beam bottom steel is not continuous through the joint, but is lapped within the column diameter dimension. This lap length is insufficient for full reinforcing development, resulting in limited positive flexural capacity and force-controlled brittle failures.
- Garage column bar splices are insufficient for full development of reinforcing.
- Rectangular column stirrups are spaced too far apart through the column length to develop the probable column flexural strength.
- Beam column joints, at spandrel beams, do not have ties within the joint.
- The steep grade results in a flexible frame on the north side relative to the southern walls, causing a torsional response in the E-W direction.
- Exterior ramp walls are connected to the main floor diaphragm via short segments of thin ramp slabs, limiting the force that can be transferred to the walls.
- Horizontal wall segments in the punched ramp walls lack sufficient reinforcing to couple the vertical piers.

The large number of items listed above may collectively affect the seismic performance of the building such that local failures may occur collectively, negatively affecting the global building performance. The shared wall at the south edge of the parking garage will likely not influence the behavior, response or potential damage to the Millberry Union building located above the garage.

Structural deficiency	Affects rating?	Structural deficiency	Affects rating?
Lateral system stress check (wall shear, column shear or flexure, or brace axial as applicable)	Y	Openings at shear walls (concrete or masonry)	Y
Load path	Y	Liquefaction	N
Adjacent buildings	N	Slope failure	N
Weak story	N	Surface fault rupture	N
Soft story	N	Masonry or concrete wall anchorage at flexible diaphragm	N
Geometry (vertical irregularities)	N	URM wall height-to-thickness ratio	N
Torsion	Y	URM parapets or cornices	N
Mass – vertical irregularity	N	URM chimney	N
Cripple walls	N	Heavy partitions braced by ceilings	N
Wood sills (bolting)	N	Appendages	N
Diaphragm continuity	N		

**Summary of review of nonstructural life-safety concerns, including at exit routes.**

A detailed assessment of nonstructural systems has not been performed. No life-safety concerns were observed during the site walk.

UCOP non-structural checklist item	Life safety hazard?	UCOP non-structural checklist item	Life safety hazard?
Heavy ceilings, feature or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate	None observed	Unrestrained hazardous materials storage	None observed
Heavy masonry or stone veneer above exit ways and public access areas	None observed	Masonry chimneys	None observed
Unbraced masonry parapets, cornices or other ornamentation above exit ways and public access areas	None observed	Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc.	None observed

### Basis of seismic performance level rating

The building’s Seismic Performance Level rating of V can be attributed to the structural deficiencies identified above. The influence of the Millberry Union building, when subjected to seismic shaking, may also have an effect on the seismic response and potential for damage in a major earthquake.

### Recommendations for further evaluation or retrofit:

We recommend that the University perform a more detailed seismic evaluation to determine the size and scope of the retrofit required to achieve a Seismic Performance Level IV. Applicable retrofit measures may include adding strength to slabs and columns via fiber-reinforced polymer. The addition of concrete walls or other similarly stiff elements is likely required to reduce stress on existing elements and balance the building’s torsional response.

### Peer review comments on rating

The structural members of the UCSF Seismic Review Committee (SRC) reviewed the evaluation on 8 January 2020 and agree with the rating of V.

Additional building data	Entry	Notes
Latitude	37.76365°	
Longitude	-122.45855°	
Are there other structures besides this one under the same CAAN#	No	
Number of stories above lowest perimeter grade	7	Top of garage is 7 levels above grade at north side of building, 2 levels below grade at south side of building
Number of stories (basements) below lowest perimeter grade	0	Garage at base of slope
Building occupiable area (OGSF)	240,000	Estimated from drawings
Risk Category per 2016 CBC 1604.5	II	
Building structural height, $h_n$	62 ft	As defined per ASCE 7-16 Section 11.2
Coefficient for period, $C_t$	0.02	ASCE 41-17 equation 4-4 and 7-18
Coefficient for period, $\zeta$	0.9	ASCE 41-17 equation 4-4 and 7-18
Estimated fundamental period	0.74 sec	ASCE 41-17 equation 4-4 and 7-18
Site data		
975 yr hazard parameters $S_s, S_1$	1.543, 0.608	<a href="https://hazards.atcouncil.org/">https://hazards.atcouncil.org/</a>



Additional building data	Entry	Notes
Site class	D	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Site class basis	Estimated	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Site parameters $F_a, F_v$	1.0, 1.7	<a href="https://hazards.atcouncil.org/">https://hazards.atcouncil.org/</a> describes *null for $F_v$ (estimated)
Ground motion parameters $S_{cs}, S_{c1}$	1.543, 1.034	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
$S_a$ at building period	1.54	Calculated
Site $V_{s30}$	305 m/s	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
$V_{s30}$ basis	Estimated	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Liquefaction potential	No	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Liquefaction assessment basis	Estimated	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Landslide potential	No	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Landslide assessment basis	Sloping Site	Rutherford + Chekene Study, 2006
Active fault-rupture hazard identified at site?	No	UCSF Group 2 Buildings, Geotechnical Characteristics and Geohazards, Egan (2019)
Site-specific ground motion study?	No	
Applicable code		
Applicable code or approx. date of original construction	Unit No. 2 Drawings Dated 1958	
Applicable code for partial retrofit	None	No partial retrofit known
Applicable code for full retrofit	None	No full retrofit known
Model building data		
Model building type North-South	C1 & C2 Conc.	
Model building type East-West	C1 & C2 Conc.	
FEMA P-154 score	N/A	Not included here because we performed ASCE 41 Tier 1 evaluation.
Previous ratings		
Most recent rating	IV	In spreadsheet. Basis for rating is unknown
Date of most recent rating	-	Rating date is unknown
2 <sup>nd</sup> most recent rating	-	
Date of 2 <sup>nd</sup> most recent rating	-	


Additional building data	Entry	Notes
<b>Appendices</b>		
ASCE 41 Tier 1 checklist included here?	Yes	Refer to attached checklist file




# **Appendix A**


## Drawing Images







Garage Plans







Garage Plans







Garage Plans





Garage Plans





TIED COLUMNS


SPIRALLY REINF. COLUMNS

TYPICAL COLUMN DETAILS


NOTES:

- ① - 2" typically below beam, tapered haunch at column top, continuous haunch, or slab soffit; i.e. deepest member framing into column.
- ② - Typical at ea. end of spiral wrapping - Two complete turns, with end of spiral hooking around col. vert.
- X = Dowel extension - a. Typically - to bottom of spread footing, ending in 1'-0" bend. See details. b. At Caisson Footings - Straight dowels, no bends, extending 20 dia. or 3'-0" min. below top of footing.
- y = Typical splice lap - 20 dia. or 3'-0" min. unless otherwise indicated on details.
- ③ - Ends of verticals cut square. Grind to horiz. surface to permit future welded extensions.






**Slab-Column Detail**



**Frame Beam Details**



Punched Exterior Ramp Wall Elevation



## Appendix B

### Checklists

UC Campus:	San Francisco			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	MP/LZ	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	1	of	3

## ASCE 41-17 Collapse Prevention Basic Configuration Checklist

### LOW SEISMICITY

#### BUILDING SYSTEMS - GENERAL

	Description
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>LOAD PATH: The structure contains a complete, well-defined load path, including structural elements and connections, that serves to transfer the inertial forces associated with the mass of all elements of the building to the foundation. (Commentary: Sec. A.2.1.1. Tier 2: Sec. 5.4.1.1)</p> <p><b>Comments: Diaphragm and frames are flat-slabs and columns are anchored into foundation.</b></p>
<b>C NC N/A U</b> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p>ADJACENT BUILDINGS: The clear distance between the building being evaluated and any adjacent building is greater than 0.25% of the height of the shorter building in low seismicity, 0.5% in moderate seismicity, and 1.5% in high seismicity. (Commentary: Sec. A.2.1.2. Tier 2: Sec. 5.4.1.2)</p> <p><b>Comments: Garage building is tied to the adjacent Union building along Grids M and O with slab dowels (at Levels A &amp; B) and a shared retaining wall (spanning between Level C to E).</b></p>
<b>C NC N/A U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<p>MEZZANINES: Interior mezzanine levels are braced independently from the main structure or are anchored to the seismic-force-resisting elements of the main structure. (Commentary: Sec. A.2.1.3. Tier 2: Sec. 5.4.1.3)</p> <p><b>Comments:</b></p>

#### BUILDING SYSTEMS - BUILDING CONFIGURATION

	Description
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>WEAK STORY: The sum of the shear strengths of the seismic-force-resisting system in any story in each direction is not less than 80% of the strength in the adjacent story above. (Commentary: Sec. A.2.2.2. Tier 2: Sec. 5.4.2.1)</p> <p><b>Comments: Shear strengths between stories are similar</b></p>
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>SOFT STORY: The stiffness of the seismic-force-resisting system in any story is not less than 70% of the seismic-force-resisting system stiffness in an adjacent story above or less than 80% of the average seismic-force-resisting system stiffness of the three stories above. (Commentary: Sec. A.2.2.3. Tier 2: Sec. 5.4.2.2)</p> <p><b>Comments: Shear stiffnesses between stories are similar</b></p>
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>VERTICAL IRREGULARITIES: All vertical elements in the seismic-force-resisting system are continuous to the foundation. (Commentary: Sec. A.2.2.4. Tier 2: Sec. 5.4.2.3)</p> <p><b>Comments: Frames and walls are continuous to the foundation</b></p>

**Note:** C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	San Francisco			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	MP/LZ	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	2	of	3

## ASCE 41-17 Collapse Prevention Basic Configuration Checklist

<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>GEOMETRY: There are no changes in the net horizontal dimension of the seismic-force-resisting system of more than 30% in a story relative to adjacent stories, excluding one-story penthouses and mezzanines. (Commentary: Sec. A.2.2.5. Tier 2: Sec. 5.4.2.4)</p> <p><b>Comments: One or two bays are added at each grade step</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>MASS: There is no change in effective mass of more than 50% from one story to the next. Light roofs, penthouses, and mezzanines need not be considered. (Commentary: Sec. A.2.2.6. Tier 2: Sec. 5.4.2.5)</p> <p><b>Comments: One or two bays are added at each grade step</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>TORSION: The estimated distance between the story center of mass and the story center of rigidity is less than 20% of the building width in either plan dimension. (Commentary: Sec. A.2.2.7. Tier 2: Sec. 5.4.2.6)</p> <p><b>Comments: North frame is more flexible than south frames and retaining walls at the grade steps</b></p>

### MODERATE SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW SEISMICITY)

#### GEOLOGIC SITE HAZARD

	Description
<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance do not exist in the foundation soils at depths within 50 ft (15.2m) under the building. (Commentary: Sec. A.6.1.1. Tier 2: 5.4.3.1)</p> <p><b>Comments: Liquefaction potential is negligible per Egan (2019).</b></p>
<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>SLOPE FAILURE: The building site is located away from potential earthquake-induced slope failures or rockfalls so that it is unaffected by such failures or is capable of accommodating any predicted movements without failure. (Commentary: Sec. A.6.1.2. Tier 2: 5.4.3.1)</p> <p><b>Comments: Slope failure is unlikely per Egan (2019).</b></p>
<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site are not anticipated. (Commentary: Sec. A.6.1.3. Tier 2: 5.4.3.1)</p> <p><b>Comments: Faults are adequately distant and do not pose a risk at this site per Egan (2019).</b></p>

**Note:** C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	San Francisco			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	MP/LZ	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	3	of	3

**ASCE 41-17  
Collapse Prevention Basic Configuration Checklist**

**HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR MODERATE SEISMICITY)**

**FOUNDATION CONFIGURATION**

	Description
<b>C NC N/A U</b> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p><b>OVERTURNING:</b> The ratio of the least horizontal dimension of the seismic-force-resisting system at the foundation level to the building height (base/height) is greater than <math>0.6S_a</math>. (Commentary: Sec. A.6.2.1. Tier 2: Sec. 5.4.3.3)</p> <p><b>Comments: The calculation shows noncompliance for this building; further analysis is required to assess the contribution from the retained soil and the interaction of foundation and influence from overburden</b></p>
<b>C NC N/A U</b> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p><b>TIES BETWEEN FOUNDATION ELEMENTS:</b> The foundation has ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Site Class A, B, or C. (Commentary: Sec. A.6.2.2. Tier 2: Sec. 5.4.3.4)</p> <p><b>Comments: Interior footings are not tied together by beams or directly by the slab</b></p>

**Note:** C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ/MP	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	1	of	4

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type C1

### Low Seismicity

#### Seismic-Force-Resisting System

	Description
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>REDUNDANCY: The number of lines of moment frames in each principal direction is greater than or equal to 2. (Commentary: Sec. A.3.1.1.1. Tier 2: Sec. 5.5.1.1)</p> <p><b>Comments: Every line in the building in each direction is a slab-column or beam-column moment frame.</b></p>
<b>C NC N/A U</b> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p>COLUMN AXIAL STRESS CHECK: The axial stress caused by unfactored gravity loads in columns subjected to overturning forces because of seismic demands is less than <math>0.20f_c</math>. Alternatively, the axial stress caused by overturning forces alone, calculated using the Quick Check procedure of Section 4.4.3.6, is less than <math>0.30f_c</math>. (Commentary: Sec. A.3.1.4.2. Tier 2: Sec. 5.5.2.1.3)</p> <p><b>Comments: Axial stress caused by overturning alone exceeds <math>0.3f_c</math>. (2.1 ksi compared to an acceptable 1.5 ksi.)</b></p>

#### Connections

	Description
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>CONCRETE COLUMNS: All concrete columns are doweled into the foundation with a minimum of four bars. (Commentary: Sec. A.5.3.2. Tier 2: Sec. 5.7.3.1)</p> <p><b>Comments: Dowels equal in number and size to column verticals provided.</b></p>

### Moderate Seismicity (Complete The Following Items In Addition To The Items For Low Seismicity)

#### Seismic-Force-Resisting System

	Description
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<p>REDUNDANCY: The number of bays of moment frames in each line is greater than or equal to 2. (Commentary: Sec. A.3.1.1.1. Tier 2: Sec. 5.5.1.1)</p> <p><b>Comments: Except at the base where there are two bays in the short direction before they increase with increasing grade, there are 3 to 5 bays in the short direction and at least 7 bays in the long direction.</b></p>

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ/MP	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	2	of	4

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type C1

<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>INTERFERING WALLS: All concrete and masonry infill walls placed in moment frames are isolated from structural elements. (Commentary: Sec. A.3.1.2.1. Tier 2: Sec. 5.5.2.1.1)</p> <p><b>Comments: No interfering walls. Retaining walls occur at the south and will participate in the lateral resistance.</b></p>
<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>COLUMN SHEAR STRESS CHECK: The shear stress in the concrete columns, calculated using the Quick Check procedure of Section 4.4.3.2, is less than the greater of 100 lb/in.<sup>2</sup> (0.69 MPa) or <math>2\sqrt{f_c}</math>. (Commentary: Sec. A.3.1.4.1. Tier 2: Sec. 5.5.2.1.4)</p> <p><b>Comments: Shear stress is 4.0 ksi compared to an acceptable 4.5 ksi.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>FLAT SLAB FRAMES: The seismic-force-resisting system is not a frame consisting of columns and a flat slab or plate without beams. (Commentary: Sec. A.3.1.4.3. Tier 2: Sec. 5.5.2.3.1)</p> <p><b>Comments: The main seismic force-resisting system is flat-slab moment frames.</b></p>

### High Seismicity (Complete The Following Items In Addition To The Items For Low And Moderate Seismicity)

#### Seismic-Force-Resisting System

	Description
<b>C</b> <input type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input checked="" type="radio"/> <b>U</b> <input type="radio"/>	<p>PRESTRESSED FRAME ELEMENTS: The seismic-force-resisting frames do not include any prestressed or post-tensioned elements where the average prestress exceeds the lesser of 700 lb/in.<sup>2</sup> (4.83 MPa) or <math>f_c/6</math> at potential hinge locations. The average prestress is calculated in accordance with the Quick Check procedure of Section 4.4.3.8. (Commentary: Sec. A.3.1.4.4. Tier 2: Sec. 5.5.2.3.2)</p> <p><b>Comments: There are no prestressed structural elements.</b></p>
<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>CAPTIVE COLUMNS: There are no columns at a level with height/depth ratios less than 50% of the nominal height/depth ratio of the typical columns at that level. (Commentary: Sec. A.3.1.4.5. Tier 2: Sec. 5.5.2.3.3)</p> <p><b>Comments: Columns span the full story heights uninterrupted.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p>NO SHEAR FAILURES: The shear capacity of frame members is able to develop the moment capacity at the ends of the members. (Commentary: Sec. A.3.1.4.6. Tier 2: Sec. 5.5.2.3.4)</p> <p><b>Comments: Beams and rectangular columns do not have adequate shear reinforcing to develop moment capacity.</b></p>

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ/MP	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	3	of	4

## ASCE 41-17

# Collapse Prevention Structural Checklist For Building Type C1

<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>STRONG COLUMN—WEAK BEAM:</b> The sum of the moment capacity of the columns is 20% greater than that of the beams at frame joints. (Commentary: Sec. A.3.1.4.7. Tier 2: Sec. 5.5.2.1.5)</p> <p><b>Comments: Compliant at the spandrel beams and flat slab frames.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>BEAM BARS:</b> At least two longitudinal top and two longitudinal bottom bars extend continuously throughout the length of each frame beam. At least 25% of the longitudinal bars provided at the joints for either positive or negative moment are continuous throughout the length of the members. (Commentary: A.3.1.4.8. Tier 2: Sec. 5.5.2.3.5)</p> <p><b>Comments: Spandrel beams and flat slab fail these requirements.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>COLUMN-BAR SPLICES:</b> All column-bar lap splice lengths are greater than <math>35d_b</math> and are enclosed by ties spaced at or less than <math>8d_b</math>. Alternatively, column bars are spliced with mechanical couplers with a capacity of at least 1.25 times the nominal yield strength of the spliced bar. (Commentary: Sec. A.3.1.4.9. Tier 2: Sec. 5.5.2.3.6)</p> <p><b>Comments: Column bar splices are <math>20d_b</math> or 36" min.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>BEAM-BAR SPLICES:</b> The lap splices or mechanical couplers for longitudinal beam reinforcing are not located within <math>l_b/4</math> of the joints and are not located in the vicinity of potential plastic hinge locations. (Commentary: Sec. A.3.1.4.10. Tier 2: Sec. 5.5.2.3.6)</p> <p><b>Comments: Spandrel beam and flat slab bottom steel is lapped within the column.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>COLUMN-TIE SPACING:</b> Frame columns have ties spaced at or less than <math>d/4</math> throughout their length and at or less than <math>8d_b</math> at all potential plastic hinge locations. (Commentary: Sec. A.3.1.4.11. Tier 2: Sec. 5.5.2.3.7)</p> <p><b>Comments: Circular columns are compliant and utilize spirals with 2 or 3 inch pitch. Perimeter rectangular columns have ties spaced at 12" throughout, typically larger than <math>d/4</math>, and closer spacing provided at ends (4 ties @ 3") does not extend far enough to encompass the potential hinge region.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>STIRRUP SPACING:</b> All beams have stirrups spaced at or less than <math>d/2</math> throughout their length. At potential plastic hinge locations, stirrups are spaced at or less than the minimum of <math>8d_b</math> or <math>d/4</math>. (Commentary: Sec. A.3.1.4.12. Tier 2: Sec. 5.5.2.3.7)</p> <p><b>Comments: Spandrel beam have a typical <math>d=21"</math>. Stirrups are spaced at 12", larger than <math>d/2</math>, throughout with 4 to 6 stirrups at 6" spacing at the ends, larger than <math>d/4</math>.</b></p>
<b>C</b> <input type="radio"/> <b>NC</b> <input checked="" type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<p><b>JOINT TRANSVERSE REINFORCING:</b> Beam-column joints have ties spaced at or less than <math>8d_b</math>. (Commentary: Sec. A.3.1.4.13. Tier 2: Sec. 5.5.2.3.8)</p> <p><b>Comments: No reinforcement in the joints.</b></p>

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown



UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ/MP	Checked:	KDP
Building Address:	500 Parnassus Ave, San Francisco, CA 94143			Page:	4	of	4

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type C1

<b>C</b> <b>NC</b> <b>N/A</b> <b>U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>DEFLECTION COMPATIBILITY:</b> Secondary components have the shear capacity to develop the flexural strength of the components. (Commentary: Sec. A.3.1.6.2. Tier 2: Sec. 5.5.2.5.2)  <b>Comments: All columns are assumed to participate in frame action.</b>
<b>C</b> <b>NC</b> <b>N/A</b> <b>U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>FLAT SLABS:</b> Flat slabs or plates not part of the seismic-force-resisting system have continuous bottom steel through the column joints. (Commentary: Sec. A.3.1.6.3. Tier 2: Sec. 5.5.2.5.3)  <b>Comments: All flat slabs are assumed to participate in frame action (continuous bottom steel does not occur at any location).</b>
<b>Diaphragms</b>	
<b>Description</b>	
<b>C</b> <b>NC</b> <b>N/A</b> <b>U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<b>DIAPHRAGM CONTINUITY:</b> The diaphragms are not composed of split-level floors and do not have expansion joints. (Commentary: Sec. A.4.1.1. Tier 2: Sec. 5.6.1.1)  <b>Comments: Concrete floor diaphragms continuous throughout floors.</b>
<b>Connections</b>	
<b>Description</b>	
<b>C</b> <b>NC</b> <b>N/A</b> <b>U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>UPLIFT AT PILE CAPS:</b> Pile caps have top reinforcement, and piles are anchored to the pile caps. (Commentary: Sec. A.5.3.8. Tier 2: Sec. 5.7.3.5)  <b>Comments: Foundations are spread footings and belled caissons. This building does not have piles or pile caps.</b>

Note: **C** = Compliant   **NC** = Noncompliant   **N/A** = Not Applicable   **U** = Unknown

UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ	Checked:	KDP
Building Address:	500 Parnassus Avenue, San Francisco, CA 94133			Page:	1	of	3

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type C2-C2A

Low and Moderate Seismicity							
Seismic-Force-Resisting System							
				Description			
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>COMPLETE FRAMES: Steel or concrete frames classified as secondary components form a complete vertical-load-carrying system. (Commentary: Sec. A.3.1.6.1. Tier 2: Sec. 5.5.2.5.1)</p> <p><b>Comments: All frames are assumed to participate in frame action.</b></p>			
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>				
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>REDUNDANCY: The number of lines of shear walls in each principal direction is greater than or equal to 2. (Commentary: Sec. A.3.2.1.1. Tier 2: Sec. 5.5.1.1)</p> <p><b>Comments: Four curved ramped walls exist at each level. Slab-column frames are assumed to participate providing additional lines of resistance.</b></p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>SHEAR STRESS CHECK: The shear stress in the concrete shear walls, calculated using the Quick Check procedure of Section 4.4.3.3, is less than the greater of 100 lb/in.<sup>2</sup> (0.69 MPa) or <math>2\sqrt{f'_c}</math>. (Commentary: Sec. A.3.2.2.1. Tier 2: Sec. 5.5.3.1.1)</p> <p><b>Comments: Compliant at ramp walls (0.4 ksi compared to an acceptable 3.5 ksi).</b></p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>REINFORCING STEEL: The ratio of reinforcing steel area to gross concrete area is not less than 0.0012 in the vertical direction and 0.0020 in the horizontal direction. (Commentary: Sec. A.3.2.2.2. Tier 2: Sec. 5.5.3.1.3)</p> <p><b>Comments: Wall steel exceeds minimum ratios, 0.0025 minimum is provided in both directions.</b></p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
Connections							
				Description			
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>WALL ANCHORAGE AT FLEXIBLE DIAPHRAGMS: Exterior concrete or masonry walls that are dependent on flexible diaphragms for lateral support are anchored for out-of-plane forces at each diaphragm level with steel anchors, reinforcing dowels, or straps that are developed into the diaphragm. Connections have strength to resist the connection force calculated in the Quick Check procedure of Section 4.4.3.7. (Commentary: Sec. A.5.1.1. Tier 2: Sec. 5.7.1.1)</p> <p><b>Comments: No flexible diaphragms are present.</b></p>			
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>				
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>TRANSFER TO SHEAR WALLS: Diaphragms are connected for transfer of seismic forces to the shear walls. (Commentary: Sec. A.5.2.1. Tier 2: Sec. 5.7.2)</p> <p><b>Comments: Exterior ramp walls are not adequately connected to the main diaphragm, limited by ramp connection.</b></p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
<b>C</b>	<b>NC</b>	<b>N/A</b>	<b>U</b>	<p>FOUNDATION DOWELS: Wall reinforcement is doweled into the foundation with vertical bars equal in size and spacing to the vertical wall reinforcing directly above the foundation. (Commentary: Sec. A.5.3.5. Tier 2: Sec. 5.7.3.4)</p> <p><b>Comments: Wall steel is doweled into the foundation.</b></p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				

Note: **C** = Compliant    **NC** = Noncompliant    **N/A** = Not Applicable    **U** = Unknown

UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ	Checked:	KDP
Building Address:	500 Parnassus Avenue, San Francisco, CA 94133			Page:	2	of	3

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type C2-C2A

### High Seismicity (Complete the Following Items in Addition To The Items For Low And Moderate Seismicity)

#### Seismic-Force-Resisting System

	Description
<b>C NC N/A U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>DEFLECTION COMPATIBILITY:</b> Secondary components have the shear capacity to develop the flexural strength of the components. (Commentary: Sec. A.3.1.6.2. Tier 2: Sec. 5.5.2.5.2)  <b>Comments: All slabs, beams, and columns are assumed to participate in frame action.</b>
<b>C NC N/A U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>FLAT SLABS:</b> Flat slabs or plates not part of the seismic-force-resisting system have continuous bottom steel through the column joints. (Commentary: Sec. A.3.1.6.3. Tier 2: Sec. 5.5.2.5.3)  <b>Comments: Flat slabs are assumed to participate in frame action.</b>
<b>C NC N/A U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>COUPLING BEAMS:</b> The ends of both walls to which the coupling beam is attached are supported at each end to resist vertical loads caused by overturning. (Commentary: Sec. A.3.2.2.3. Tier 2: Sec. 5.5.3.2.1)  <b>Comments: No coupling beams in the building.</b>

#### Diaphragms (Stiff or Flexible)

	Description
<b>C NC N/A U</b> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	<b>DIAPHRAGM CONTINUITY:</b> The diaphragms are not composed of split-level floors and do not have expansion joints. (Commentary: Sec. A.4.1.1. Tier 2: Sec. 5.6.1.1)  <b>Comments: Diaphragms are generally continuous, without joints.</b>
<b>C NC N/A U</b> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<b>OPENINGS AT SHEAR WALLS:</b> Diaphragm openings immediately adjacent to the shear walls are less than 25% of the wall length. (Commentary: Sec. A.4.1.4. Tier 2: Sec. 5.6.1.3)  <b>Comments: Exterior ramp walls are connected to the main diaphragm only by the ramp. No significant openings occur next to perimeter walls.</b>

#### Flexible Diaphragms

	Description
<b>C NC N/A U</b> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<b>CROSS TIES:</b> There are continuous cross ties between diaphragm chords. (Commentary: Sec. A.4.1.2. Tier 2: Sec. 5.6.1.2)  <b>Comments: Not applicable to this building.</b>

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	UCSF - Parnassus			Date:	06/12/2020		
Building CAAN:	2212.1	Auxiliary CAAN:		By Firm:	Simpson Gumpertz & Heger		
Building Name:	Millberry Garage			Initials:	LZ	Checked:	KDP
Building Address:	500 Parnassus Avenue, San Francisco, CA 94133			Page:	3	of	3

**ASCE 41-17**  
**Collapse Prevention Structural Checklist For Building Type C2-C2A**

<b>C</b> <input type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input checked="" type="radio"/> <b>U</b> <input type="radio"/>	<b>STRAIGHT SHEATHING:</b> All straight-sheathed diaphragms have aspect ratios less than 2-to-1 in the direction being considered. (Commentary: Sec. A.4.2.1. Tier 2: Sec. 5.6.2)  <b>Comments: Not applicable to this building.</b>
<b>C</b> <input type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input checked="" type="radio"/> <b>U</b> <input type="radio"/>	<b>SPANS:</b> All wood diaphragms with spans greater than 24 ft (7.3 m) consist of wood structural panels or diagonal sheathing. (Commentary: Sec. A.4.2.2. Tier 2: Sec. 5.6.2)  <b>Comments: Not applicable to this building.</b>
<b>C</b> <input type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input checked="" type="radio"/> <b>U</b> <input type="radio"/>	<b>DIAGONALLY SHEATHED AND UNBLOCKED DIAPHRAGMS:</b> All diagonally sheathed or unblocked wood structural panel diaphragms have horizontal spans less than 40 ft (12.2 m) and aspect ratios less than or equal to 4-to-1. (Commentary: Sec. A.4.2.3. Tier 2: Sec. 5.6.2)  <b>Comments: Not applicable to this building.</b>
<b>C</b> <input checked="" type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input type="radio"/> <b>U</b> <input type="radio"/>	<b>OTHER DIAPHRAGMS:</b> Diaphragms do not consist of a system other than wood, metal deck, concrete, or horizontal bracing. (Commentary: Sec. A.4.7.1. Tier 2: Sec. 5.6.5)  <b>Comments: Diaphragms are all reinforced concrete.</b>
<b>Connections</b>	
	<b>Description</b>
<b>C</b> <input type="radio"/> <b>NC</b> <input type="radio"/> <b>N/A</b> <input checked="" type="radio"/> <b>U</b> <input type="radio"/>	<b>UPLIFT AT PILE CAPS:</b> Pile caps have top reinforcement, and piles are anchored to the pile caps. (Commentary: Sec. A.5.3.8. Tier 2: Sec. 5.7.3.5)  <b>Comments: Foundations are spread footings and belled caissons. This building does not have piles or pile caps.</b>

Note: **C** = Compliant    **NC** = Noncompliant    **N/A** = Not Applicable    **U** = Unknown

# Appendix C

## Tier 1 Calculations

**SIMPSON GUMPERTZ & HEGER**



Engineering of Structures  
and Building Enclosures


CLIENT UCSF  
SUBJECT Milberry Garage Tier 1 - Quick Checks: BSE-C Hazard

SHEET NO. \_\_\_\_\_  
PROJECT NO. 197042.00  
DATE 12/30/2019  
BY \_\_\_\_\_  
CHECKED BY KDP

**Hazard Level BSE-C (BSE-2E)**

MCE <sub>R</sub> ground motion (period=0.2s)	S <sub>s</sub>	1.543 g
MCE <sub>R</sub> ground motion (period=1.0s)	S <sub>1</sub>	0.608 g
Site amplification factor at 0.2s	F <sub>a</sub>	1.0
Site amplification factor at 1.0s	F <sub>v</sub>	1.7
Site modified spectral response (0.2s)	S <sub>XS</sub>	1.543 g
Site modified spectral response (1.0s)	S <sub>X1</sub>	1.034 g
Long-period transition period (s)	T <sub>L</sub>	12 sec
	T <sub>0</sub>	0.134 sec
	T <sub>S</sub>	0.670 sec

T	S <sub>a</sub>
sec	g
0.0	0.617
0.134	1.543
0.670	1.543
0.67	1.543
0.77	1.342
0.87	1.188
0.97	1.066
1.1	0.966
2.0	0.517
3.0	0.345
4.0	0.258
6.0	0.172
8.0	0.129
10.0	0.103
12.0	0.086



**Approximate Period of Structure**

System // Flat slab

h <sub>n</sub>	61.98 ft
β	0.75
C <sub>t</sub>	0.020
<b>T</b>	<b>0.442 sec</b>
<b>S<sub>a</sub></b>	<b>1.543 g</b>

**SIMPSON GUMPERTZ & HEGER**



Engineering of Structures  
and Building Enclosures

CLIENT UCSF

SUBJECT Millberry Garage Tier 1 - Quick Checks: Flat Loads

SHEET NO. \_\_\_\_\_

PROJECT NO. 197042.00-UCSF

DATE 07 October 2019

BY LZ

CHECKED \_\_\_\_\_

**Typical Garage Level G - Level A**

Material	Self-Weight (psf)	SDL (psf)	Gravity (psf)	Seismic (psf)	Remarks
12" Concrete Slab	150.0	-	150.0	150.0	
Tapered Drop Panels	22.0	-	22.0	22.0	Distributed over average 32'x24' bay
MEP/Sprinkler/Miscellaneous	-	5.0	5.0	5.0	
<i>Sum of Dead Loads</i>	<b>172.0</b>	<b>5.0</b>	<b>177.0</b>	<b>177.0</b>	
<i>Sum of Live Loads</i>	-	-	<b>40.0</b>	-	
<i>Sum of Dead Plus Live Loads</i>	-	-	<b>217.0</b>	<b>177.0</b>	

**Typical Ramp Level G - Level A**

Material	Self-Weight (psf)	SDL (psf)	Gravity (psf)	Seismic (psf)	Remarks
8" Concrete Slab	100.0	-	100.0	100.0	
MEP/Sprinkler/Miscellaneous	-	2.0	2.0	2.0	
<i>Sum of Dead Loads</i>	<b>100.0</b>	<b>2.0</b>	<b>102.0</b>	<b>102.0</b>	
<i>Sum of Live Loads</i>	-	-	<b>40.0</b>	-	
<i>Sum of Dead Plus Live Loads</i>	-	-	<b>142.0</b>	<b>102.0</b>	

**Union Lobby Level 0**

Material	Self-Weight (psf)	SDL (psf)	Gravity (psf)	Seismic (psf)	Remarks
30" Concrete Slab	375.0	-	375.0	375.0	
Ceiling	-	5.0	5.0	5.0	
Floor Finish	-	25.0	25.0	25.0	
Partitions	-	0.0	0.0	10.0	
MEP/Sprinkler/Miscellaneous	-	5.0	5.0	5.0	
<i>Sum of Dead Loads</i>	<b>375.0</b>	<b>35.0</b>	<b>410.0</b>	<b>420.0</b>	
<i>Sum of Live Loads</i>	-	-	<b>100.0</b>	-	
<i>Sum of Dead Plus Live Loads</i>	-	-	<b>510.0</b>	<b>420.0</b>	



**SIMPSON GUMPERTZ & HEGER**



Engineering of Structures  
and Building Enclosures

CLIENT UCSF

SUBJECT Millberry Garage Tier 1 - Quick Checks: Flat Loads

SHEET NO. \_\_\_\_\_

PROJECT NO. 197042.00-UCSF

DATE 07 October 2019

BY LZ

CHECKED \_\_\_\_\_

**Penthouse Floor** **PH Floor**

Material	Self-Weight (psf)	SDL (psf)	Gravity (psf)	Seismic (psf)	Remarks
5" Concrete Slab	62.5	-	62.5	62.5	<i>Decked area is similar in weight</i>
Ceiling	-	5.0	5.0	5.0	
Roofing/Insulation	-	10.0	10.0	10.0	
Roof Ducts	-	5.0	5.0	10.0	
MEP/Sprinkler/Miscellaneous	-	5.0	5.0	5.0	
<i>Sum of Dead Loads</i>	<b>62.5</b>	<b>25.0</b>	<b>87.5</b>	<b>92.5</b>	
<i>Sum of Live Loads</i>	-	-	<b>20.0</b>	-	
<i>Sum of Dead Plus Live Loads</i>	-	-	<b>107.5</b>	<b>92.5</b>	

**Machinery Deck** **Mach Floor**

Material	Self-Weight (psf)	SDL (psf)	Gravity (psf)	Seismic (psf)	Remarks
4" Concrete Slab	50.0	-	50.0	50.0	
Ceiling	-	5.0	5.0	5.0	
MEP/Sprinkler/Miscellaneous	-	5.0	5.0	5.0	
<i>Sum of Dead Loads</i>	<b>50.0</b>	<b>10.0</b>	<b>60.0</b>	<b>60.0</b>	
<i>Sum of Live Loads</i>	-	-	<b>50.0</b>	-	
<i>Sum of Dead Plus Live Loads</i>	-	-	<b>110.0</b>	<b>60.0</b>	

**Penthouse Roof** **PH Roof**

Material	Self-Weight (psf)	SDL (psf)	Gravity (psf)	Seismic (psf)	Remarks
3" Concrete Slab	37.5	-	37.5	37.5	
4"x13" Joists @ 34"	15.0	-	15.0	15.0	
Ceiling	-	5.0	5.0	5.0	
Roofing/Insulation	-	10.0	10.0	10.0	
MEP/Sprinkler/Miscellaneous	-	5.0	5.0	5.0	
<i>Sum of Dead Loads</i>	<b>52.5</b>	<b>20.0</b>	<b>72.5</b>	<b>72.5</b>	
<i>Sum of Live Loads</i>	-	-	<b>20.0</b>	-	
<i>Sum of Dead Plus Live Loads</i>	-	-	<b>92.5</b>	<b>72.5</b>	



	Mass Type	Area (sf)	Length (ft)	Load (psf)	Load (plf)	Mass (kips)
<b>Penthouse Roof</b> h = 8.58'	Roof Area	360		73		26
	8" Concrete Wall Below		78		429	33
					Σ =	<b>60</b>
<b>Machinery Deck</b> h = 5.50'	Typical Area	275		60		17
	8" Concrete Wall Above		78		429	33
	8" Concrete Wall Below		58		275	16
	12" Concrete Wall Below		53		413	22
	16" Concrete Wall Below		10		550	6
				Σ =	<b>93</b>	
<b>Penthouse Floor</b> h = 10.75'	Penthouse Area	330		93		31
	Roof Area	730		93		68
	Metal Stair	25		30		1
	8" Concrete Wall Above		58		275	16
	12" Concrete Wall Above		53		413	22
	16" Concrete Wall Above		10		550	6
	12" Concrete Wall Below		94		806	76
	16" Concrete Wall Below		17		1075	18
					Σ =	<b>236</b>
<b>Ground Floor</b> h = 10.50'	Lobby Area	1,065		420		447
	Concrete Stair	115		125		14
	12" Concrete Wall Above		94		806	76
	16" Concrete Wall Above		17		1,075	18
	12" Concrete Wall Below		94		788	74
	16" Concrete Wall Below		22		1050	23
	Circular Columns Below (26" Dia Typ)					3
				Σ =	<b>656</b>	
<b>Level A</b> h = 8.85'	Garage Area	37,020		177		6553
	Ramp Area	2,975		102		303
	Concrete Stair	245		125		31
	12" Concrete Wall Above		94		788	74
	16" Concrete Wall Above		22		1,050	23
	16" Ramp Wall Parapet		370		700	259
	Circular Columns Above (26" Dia Typ)					3
	8" Concrete Wall Below		27		443	12
	12" Concrete Wall Below		115		664	76
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (24" Dia Typ)					74
	Rectangular Columns Below (24"x48" Typ)					63
Beams Below (24"x24" Typ)		300		300	90	
				Σ =	<b>7,857</b>	



	Mass Type	Area (sf)	Length (ft)	Load (psf)	Load (plf)	Mass (kips)
<b>Level B</b> h = 8.85'	Garage Area	37,020		177		6553
	Ramp Area	2,975		102		303
	Concrete Stair	245		125		31
	8" Concrete Wall Above		27		443	12
	12" Concrete Wall Above		115		664	76
	16" Concrete Wall Above		174		885	154
	16" Punched Ramp Wall Above (19% open)		196		719	141
	Circular Columns Above (24" Dia Typ)					74
	Rectangular Columns Above (24"x48" Typ)					63
	8" Concrete Wall Below		27		443	12
	12" Concrete Wall Below		115		664	76
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (26" Dia Typ)					73
	Rectangular Columns Below (24"x48" Typ)					53
	Beams Below (24"x24" Typ)		300		300	90
				$\Sigma =$	<b>8,007</b>	
<b>Level C</b> h = 8.85'	Garage Area	37,020		177		6553
	Ramp Area	2,975		102		303
	Concrete Stair	245		125		31
	8" Concrete Wall Above		27		443	12
	12" Concrete Wall Above		115		664	76
	16" Concrete Wall Above		174		885	154
	16" Punched Ramp Wall Above (19% open)		196		719	141
	Circular Columns Above (26" Dia Typ)					73
	Rectangular Columns Above (24"x48" Typ)					53
	8" Concrete Wall Below		27		443	12
	12" Concrete Wall Below		411		664	273
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (28" Dia Typ)					85
	Rectangular Columns Below (24"x48" Typ)					53
	Beams Below (24"x24" Typ)		300		300	90
				$\Sigma =$	<b>8,205</b>	
<b>Level D</b> h = 8.85'	Garage Area	37,020		177		6553
	Ramp Area	2,975		102		303
	Concrete Stair	245		125		31
	8" Concrete Wall Above		27		443	12
	12" Concrete Wall Above		411		664	273
	16" Concrete Wall Above		174		885	154
	16" Punched Ramp Wall Above (19% open)		196		719	141
	Circular Columns Above (28" Dia Typ)					85
	Rectangular Columns Above (24"x48" Typ)					53
	8" Concrete Wall Below		27		443	12
	12" Concrete Wall Below		411		664	273
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (30" Dia Typ)					98
	Rectangular Columns Below (24"x48" Typ)					53
	Beams Below (24"x24" Typ)		300		300	90
				$\Sigma =$	<b>8,426</b>	



	Mass Type	Area (sf)	Length (ft)	Load (psf)	Load (plf)	Mass (kips)
Level E h = 8.85'	Garage Area	25,550		177		4522
	Ramp Area	2,975		102		303
	Concrete Stair	245		125		31
	8" Concrete Wall Above		27		443	12
	12" Concrete Wall Above		411		664	273
	16" Concrete Wall Above		174		885	154
	16" Punched Ramp Wall Above (19% open)		196		719	141
	Circular Columns Above (30" Dia Typ)					98
	Rectangular Columns Above (24"x48" Typ)					53
	8" Concrete Wall Below		27		443	12
	14" Concrete Wall Below		352		775	272
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (32" Dia Typ)					89
	Rectangular Columns Below (24"x48" Typ)					43
	Beams Below (24"x24" Typ)		242		300	73
				Σ =		<b>6,371</b>
Level F h = 8.85'	Garage Area	25,550		177		4522
	Ramp Area	2,975		102		303
	Concrete Stair	245		125		31
	8" Concrete Wall Above		27		443	12
	14" Concrete Wall Above		352		775	272
	16" Concrete Wall Above		174		885	154
	16" Punched Ramp Wall Above (19% open)		196		719	141
	Circular Columns Above (32" Dia Typ)					89
	Rectangular Columns Above (24"x48" Typ)					43
	8" Concrete Wall Below		27		443	12
	14" Concrete Wall Below		352		775	272
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (34" Dia Typ)					100
	Rectangular Columns Below (25"x48" Typ)					44
	Beams Below (25"x24" Typ)		242		313	76
				Σ =		<b>6,367</b>
Level G h = 8.85'	Garage Area	14,000		177		2478
	Ramp Area	1,560		102		159
	Concrete Stair	115		125		14
	8" Concrete Wall Above		27		443	12
	14" Concrete Wall Above		352		775	272
	16" Concrete Wall Above		174		885	154
	16" Punched Ramp Wall Above (19% open)		196		719	141
	Circular Columns Above (34" Dia Typ)					100
	Rectangular Columns Above (25"x48" Typ)					44
	12" Concrete Wall Below		395		664	262
	14" Concrete Wall Below		107		775	83
	16" Concrete Wall Below		174		885	154
	16" Punched Ramp Wall Below (19% open)		196		719	141
	Circular Columns Below (36" Dia Typ)					52
	Rectangular Columns Below (27"x48" Typ)					60
	Beams Below (27"x24" Typ)		242		338	82
				Σ =		<b>4,209</b>

Base

Calculated Total Σ = **50,485**

**SIMPSON GUMPERTZ & HEGER**



Engineering of Structures  
and Building Enclosures

CLIENT UCSF

SUBJECT Milberry Garage Tier 1 - Quick Checks: Pseudo Seismic Force

SHEET NO. \_\_\_\_\_

PROJECT NO. 197042.00

DATE 12/30/2019

BY MP/LZ

CHECKED BY KDP

Floor	[kip] $W_i$	[ft] $h_i$	[ft] $(h_i)^k$	[kip-ft] $W_i(h_i)^k$	$C_{vi}$	[kip] $F_i$	[kip] $V_i$
A + PH*	8901	62.0	55.0	489254	0.279	21717	21717
B	8007	53.1	47.3	378933	0.216	16820	38537
C	8205	44.3	39.6	325294	0.185	14439	52976
D	8426	35.4	31.9	268983	0.153	11940	64916
E	6371	26.6	24.1	153817	0.088	6828	71743
F	6367	17.7	16.3	103701	0.059	4603	76347
G	4209	8.9	8.3	34971	0.020	1552	77899
	50485			1754954	1.00	77899	

T 0.442 sec

k 0.97

W 50485 kip

C 1.0 [Modification factor, buildings 4 stories or greater]

$S_a$  1.543 g

V 77899 kip

\* Masses at penthouse floors lumped to Level A



**Column Axial Stress Check**

**E-W direction**

axial stress check in column 4X at level H

Compressive strength of the concrete in columns	f'c	=	5 ksi
Pseudo seismic force	V	=	77899 kip
Total number of frames in E-W direction	nf	=	4
System modification factor	Ms	=	2.5 (for collapse prevention)
Base to roof height	hn	=	61.98 ft
Length of frame	L	=	153 ft
Area of the column at base	Acol	=	7.07 ft2

Axial stress due to overturning force

$$pot = \frac{(1/Ms)(2/3)(V*hn/Lnf)(1/Acol)}{297.77 \text{ ksf}} = 2.07 \text{ ksi}$$

limiting axial stress in column epr checklist C1

$$0.3f'c = 1.5 \text{ ksi} < 2.07 \text{ ksi} \text{ NG}$$

**N-S direction**

axial stress check in column 4X at level H

Compressive strength of the concrete in columns	f'c	=	5 ksi
Pseudo seismic force	V	=	77899 kip
Total number of frames in N-S direction	nf	=	8
System modification factor	Ms	=	2.5 (for collapse prevention)
Base to roof height	hn	=	61.98 ft
Length of frame	L	=	96 ft
Area of the column at base	Acol	=	7.07 ft2

Axial stress due to overturning force

$$pot = \frac{(1/Ms)(2/3)(V*hn/Lnf)(1/Acol)}{237.29 \text{ ksf}} = 1.65 \text{ ksi}$$

limiting axial stress in column epr checklist C1

$$0.3f'c = 1.5 \text{ ksi} < 1.65 \text{ ksi} \text{ NG}$$



**Column Shear Stress Check**

**E-W direction**

shear stress check in column 4X at level H

Compressive strength of the concrete in columns	f'c	=	5 ksi
Story shear	Vj	=	77899 kip
Total number of frames in E-W direction	nf	=	4
Total number of columns	nc	=	24
System modification factor	Ms	=	2 (for collapse prevention)
Summation of the area of all columns	Ac	=	89.33 ft2

Shear stress

$$vj\_avg = \frac{(1/Ms)(nc/(nc-nf))(Vj/Acol)}{523.25 \text{ ksf}}$$

$$vj\_avg = 3.63 \text{ ksi}$$

limiting shear stress in column per checklist C1

$$100\text{psi} = 0.1 \text{ ksi}$$

$$2\text{sqrt}(f'c) = 4.47 \text{ ksi}$$

$$\max(100\text{psi}, 2\text{sqrt}(f'c)) = 4.47 \text{ ksi} > 3.63 \text{ ksi}$$

OK

**N-S direction**

shear stress check in column 4X at level H

Compressive strength of the concrete in columns	f'c	=	5 ksi
Story shear	Vj	=	77899 kip
Total number of frames in N-S direction	nf	=	8
Total number of columns	nc	=	32
System modification factor	Ms	=	2 (for collapse prevention)
Summation of the area of all columns	Ac	=	89.33 ft2

Shear stress

$$vj\_avg = \frac{(1/Ms)(nc/(nc-nf))(Vj/Acol)}{581.39 \text{ ksf}}$$

$$vj\_avg = 4.04 \text{ ksi}$$

limiting shear stress in column per checklist C1

$$100\text{psi} = 0.1 \text{ ksi}$$

$$2\text{sqrt}(f'c) = 4.47 \text{ ksi}$$

$$\max(100\text{psi}, 2\text{sqrt}(f'c)) = 4.47 \text{ ksi} > 4.04 \text{ ksi}$$

OK

**SIMPSON GUMPERTZ & HEGER**



Engineering of Structures  
and Building Enclosures

CLIENT UCSF  
SUBJECT Milberry Garage Tier 1 - Quick Checks: Wall Shear Stress

SHEET NO. \_\_\_\_\_  
PROJECT NO. 197042.00  
DATE 1/08/2020  
BY \_\_\_\_\_ LZ  
CHECKED BY \_\_\_\_\_ KDP

**Wall Shear Stress Check**

**E-W direction**

shear stress check in ramp walls

Compressive strength of the concrete in walls	f'c	=	3 ksi
Story shear	Vj	=	77899 kip
Total approx. length in E-W direction	lw	=	250.5 ft
Thickness of walls	tw	=	1.33 ft
System modification factor	Ms	=	4.5 (for collapse prevention)
Summation of the area of walls	Aw	=	334.00 ft2

Shear stress

$$v_{j\_avg} = \frac{(1/M_s)(V_j/A_w)}{51.83 \text{ ksf}} = 0.36 \text{ ksi}$$

limiting shear stress in column per checklist C2

$$100\text{psi} = 0.1 \text{ ksi}$$

$$2\text{sqrt}(f'c) = 3.46 \text{ ksi}$$

$$\max(100\text{psi}, 2\text{sqrt}(f'c)) = 3.46 \text{ ksi} > 0.36 \text{ ksi}$$

OK

**N-S direction**

shear stress check in ramp walls

Compressive strength of the concrete in walls	f'c	=	3 ksi
Story shear	Vj	=	77899 kip
Total approx. length in E-W direction	lw	=	228 ft
Thickness of walls	tw	=	1.33 ft
System modification factor	Ms	=	4.5 (for collapse prevention)
Summation of the area of walls	Aw	=	304.00 ft2

Shear stress

$$v_{j\_avg} = \frac{(1/M_s)(V_j/A_w)}{56.94 \text{ ksf}} = 0.40 \text{ ksi}$$

limiting shear stress in column per checklist C2

$$100\text{psi} = 0.1 \text{ ksi}$$

$$2\text{sqrt}(f'c) = 3.46 \text{ ksi}$$

$$\max(100\text{psi}, 2\text{sqrt}(f'c)) = 3.46 \text{ ksi} > 0.40 \text{ ksi}$$

OK



**SIMPSON GUMPERTZ & HEGER**



Engineering of Structures  
and Building Enclosures

CLIENT UCSF  
SUBJECT Milberry Garage Tier 1 - Quick Checks: Wall Reinforcing Ratio

SHEET NO. \_\_\_\_\_  
PROJECT NO. 197042.00  
DATE 01/08/2020  
BY \_\_\_\_\_ LZ  
CHECKED BY \_\_\_\_\_ KDP

**Typical Wall Reinforcing Ratio Check**

Wall Thickness	Horizontal Reinforcing				Vertical Reinforcing			
	Curtains	Size	Spacing	Ratio	Curtains	Size	Spacing	Ratio
6	1	#4	12	0.0028	1	#4	12	0.0028
8	2	#4	18	0.0028	2	#4	18	0.0028
10	2	#4	16	0.0025	2	#4	16	0.0025
12	2	#4	12	0.0028	2	#4	12	0.0028
14	2	#5	15	0.0030	2	#5	12	0.0037
16	2	#5	12	0.0032	2	#5	10	0.0039