

Text in green is to be part of UCSF building database and may be part of UCOP database

4-8-2020

UCSF Building Seismic Ratings

1326 3RD AVENUE

CAAN #2276

1326 3rd AVENUE, SAN FRANCISCO, CA 94122

UCSF Campus: Parnassus



4/8/2019



Plan



West Elevation

Rating summary	Entry	Notes
UC Seismic Performance Level (rating)	V	Findings based on drawing review and ASCE 41-17 Tier 1 evaluation ¹
Rating basis	Tier 1	ASCE 41-17
Date of rating	2020	
Recommended UCSF priority category for retrofit	Priority B	Priority A = Retrofit ASAP Priority B=Retrofit at next permit application for modification
Ballpark total project cost to retrofit to IV rating	High	See recommendations on further evaluation and retrofit.
Is 2018-2019 rating required by UCOP?	Yes	
Further evaluation recommended?	No	

¹ The evaluations at UCSF translate the Tier 1 evaluation to a Seismic Performance Level rating using professional judgment discussed among the Seismic Review Committee. Non-compliant items in the Tier 1 evaluation do not automatically put a building into a particular rating category, but such items are evaluated along with the combination of building features and potential deficiencies, focused on the potential for collapse or serious damage to the gravity supporting structure that may threaten occupant safety.

Building information used in this evaluation

- Architectural Floor Plans, “1326 3RD Avenue,” dated 31 July 1974 (1 Sheet)
- Architectural Drawings by Scheinhotz Associates and VDK Architects, “UCSF Housing 1326 3rd Ave. San Francisco, CA,” dated 30 November 1990 (6 sheets).
- Architectural Drawings, “1326 Third Avenue Cosmetic Upgrades,” dated 1 June 2006 (3 sheets).

Scope for completing this form

Architectural drawings were reviewed and an ASCE 41-17 Tier 1 evaluation was performed. A site visit was made on December 5, 2019 where the building exterior and garage space were observed. Access to other portions of the building was not available.

Brief description of structure

The building functions as graduate student housing. It was reportedly built in 1912 as a single-family home. There is an apartment on the first and second floors over a basement with garage. The main floor plate is approximately 49 ft north-south by 25 ft east-west.

Identification of Levels: Levels are identified on plan as Basement, First Floor, Second Floor, and Attic. The site slopes downward toward the north. The basement (approximately 10'-0") contains a garage to the northeast and utilities to the west. The first floor (approximately 10'-6") consists of a kitchen, living room, dining room, foyer, bedroom, and bathroom. The second floor (approximately 10'-6") consists of four bedrooms and two bathrooms. The attic (approximately 8'-0") is open and not accessible to students. It extends over approximately the front 16'-9" of the building. A door at the east side provides access to the roof over Level 2. The front of the attic is sloped to match adjacent properties. The roof is otherwise flat. The basement/garage is at grade/street level and is used as the base of the building for this evaluation.

Foundation system: Existing foundation drawings are not available. It is presumed there are continuous footings below bearing walls. During the site visit on December 5, 2019, continuous concrete stem wall footings were observed around the ground floor level.

Structural system for vertical (gravity) load: Drawings showing the existing framing are not available. It is presumed based on the age of the building that wood joists span to load bearing wood framed walls.

Structural system for lateral forces: Drawings showing the existing framing are not available. It is presumed based on the age of the building that a sheathed diaphragm distributes load to the interior and exterior wood-framed walls sheathed with gypsum board and/or plaster. There was a ceiling in the garage space, so it could not be determined if the sheathing in the first floor was straight or diagonal. Diagonal sheathing was found on the exterior of the street-side garage wall. Where visible, straight wall sheathing was found on the side walls. No mudsill bolts were observed. The cripple wall windows on the rear wall have been sheathed with plywood and unknown nailing.

Building Code: The building was reportedly constructed in 1912, prior to a building code being enacted. However, no documentation was available to confirm the construction date.

Building Condition: What could be observed of the building structure appeared to be in fair condition; however, most of the structure was concealed behind finishes. The wood around some windows had degraded. The stem wall concrete was poorly consolidated and there is extensive efflorescence and some spalling, especially at the rear of the basement. The exterior patio and stair on the south side of the house were in good condition, including the connector hardware.

Building response in 1989 Loma Prieta Earthquake: The report titled “Performance of UCSF Buildings During the October 17, 1989 Loma Prieta Earthquake” by Impell Corporation stated the exterior and interior of the building was inspected after the earthquake and no damage was observed.

Brief description of seismic deficiencies and expected seismic performance including structural behavior modes

- The building relies on interior and exterior walls for shear resistance. There is not enough wall present to pass the Tier 1 quick check in the transverse or longitudinal direction in any story.
- Based on the age of construction, the walls between levels are not expected to be detailed to transfer shear and overturning forces between levels.
- The building is located on a sloped site. However, there is a significant length of wall on the downhill side of the building.
- The building is built to the property line with virtually no separation between the neighboring buildings to the north and south. The floor levels do not align with the adjacent buildings due to the sloped site.
- The garage cripple walls were primarily sheathed with plaster and gypsum board. Where sheathing could be observed, it was straight on the side walls and diagonal on the street-side wall. No mudsill bolts were observed.

Structural deficiency	Affects rating?	Structural deficiency	Affects rating?
Lateral system stress check (wall shear, column shear or flexure, or brace axial as applicable)	Y	Openings at shear walls (concrete or masonry)	N
Load path	Y	Liquefaction	N
Adjacent buildings	Y	Slope failure	N
Weak story	Y	Surface fault rupture	N
Soft story	N	Masonry or concrete wall anchorage at flexible diaphragm	N
Geometry (vertical irregularities)	N	URM wall height-to-thickness ratio	N
Torsion	N	URM parapets or cornices	N
Mass – vertical irregularity	N	URM chimney	N
Cripple walls	Y	Heavy partitions braced by ceilings	N
Wood sills (bolting)	Y	Appendages	N
Diaphragm continuity	N		

Summary of review of non-structural life-safety concerns, including at exit routes.²

The facilities maintenance technician assisting with the site visit noted that the building does not have a fireplace.

Anchorage or bracing of the basement water heater and furnace was not observed. The furnace did have a flexible connection to the gas line.

UCOP non-structural checklist item	Life safety hazard?	UCOP non-structural checklist item	Life safety hazard?
Heavy ceilings, feature or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate	None Observed	Unrestrained hazardous materials storage	None Observed
Heavy masonry or stone veneer above exit ways and public access areas	None Observed	Masonry chimneys	None Observed
Unbraced masonry parapets, cornices or other ornamentation above exit ways and public access areas	None Observed	Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc.	Observed in basement

Basis of Seismic Performance Level Rating

The length of wall in the subject building is well below the amount required by the ASCE 41 Tier 1 procedures, and connections between walls between levels of the building and to the foundation are not adequate for resisting

² For these Tier 1 evaluations, we do not visit all spaces of the building; we rely on campus staff to report to us their understanding of if and where non-structural hazards may occur.

seismic loading. The building is listed as Priority B because there is a relatively low risk to occupant life-safety posed by conventional wood-framed construction.

Recommendations for further evaluation or retrofit

No further evaluation of this building is recommended. There is relatively low risk to occupant life-safety posed by this type of building based on historical performance of similar building types. It is recommended that work to improve the seismic performance of the building be included with any future renovation requiring a building permit.

Peer review comments on rating

The structural members of the UCSF Seismic Review Committee (SRC) reviewed the evaluation on January 8, 2020 and are unanimous that the rating is V.

Additional building data	Entry	Notes
Latitude	37.76389	
Longitude	-122.45968	
Are there other structures besides this one under the same CAAN#	No	
Number of stories above lowest perimeter grade	4	
Number of stories (basements) below lowest perimeter grade	0	
Building occupiable area (OGSF)	3,412 sf	
Risk Category per 2016 CBC 1604.5	II	
Building structural height, h_n	35 ft	Structural height defined per ASCE 7-16 Section 11.2
Coefficient for period, C_t	0.02	Per ASCE 41-17 equation 4-4
Coefficient for period, β	0.75	Per ASCE 41-17 equation 4-4
Estimated fundamental period	0.288 sec	Per ASCE 41-17 equation 4-4
Site data		
975 yr hazard parameters S_s, S_1	1.547, 0.610	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)
Site class	C	
Site class basis	Geotech Parameters	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)
Site parameters F_a, F_v	1.200, 1.400	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)
Ground motion parameters S_{cs}, S_{c1}	1.856, 0.854	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)
S_o at building period	1.856	
Site V_{s30}	490 m/s	
V_{s30} basis	Geotech Parameters	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)
Liquefaction potential/basis	No	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)
Landslide potential/basis	No	UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)

Active fault-rupture hazard identified at site?	No	
Site-specific ground motion study?	No	
Applicable code		
Applicable code or approx. date of original construction	Built: 1912	Reported date, not confirmed
Applicable code for partial retrofit	None	No partial retrofit known
Applicable code for full retrofit	None	No full retrofit known
Model building data		
Model building type North-South	W1 : Wood Light Frames	
Model building type East-West	W1: Wood Light Frames	
FEMA P-154 score	N/A	Not included here because an ASCE 41 Tier 1 evaluation was performed.
Previous ratings		
Most recent rating	V	2013 Report
Date of most recent rating	10/7/2013	Basis: Qualitative assessment based on drawing review
2 nd most recent rating	-	
Date of 2 nd most recent rating	-	
3 rd most recent rating	-	
Date of 3 rd most recent rating	-	
Appendices		
ASCE 41 Tier 1 checklist included here?	Yes	Refer to attached checklist file

Appendix A

Additional Images




Figure 1 - Basement/Garage Floor Plan




Figure 2 - First Floor Plan




Figure 3 - Second Floor Plan




Figure 4 – Roof and Attic Floor Plan



Figure 5 – Front (West) of Building



Figure 6 - Building Separation to the North (Left) and South (Right)



Figure 7 – Concrete Condition at Garage Area



Figure 8 – Concrete Condition at Rear (East) Wall



Figure 9 – Sheathing at Rear (East) Cripple Wall




Figure 10 – Diagonal Sheathing at Front (West) Wall without Sill Bolts



Figure 11 – Unanchored Furnace and Water Heater, both with Flexible Gas Lines



Figure 12 – Rear Exterior Stairs

Appendix B

ASCE 41- 17 Tier 1 Checklists (Structural)

UC Campus:	San Francisco			Date:	4/8/2020		
Building CAAN:	2276	Auxiliary CAAN:		By Firm:	Estructure		
Building Name:	1326 3 rd Avenue			Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122			Page:	1	of	3

ASCE 41-17 Collapse Prevention Basic Configuration Checklist

LOW SEISMICITY

BUILDING SYSTEMS - GENERAL

	Description
C NC N/A U <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p>LOAD PATH: The structure contains a complete, well-defined load path, including structural elements and connections, that serves to transfer the inertial forces associated with the mass of all elements of the building to the foundation. (Commentary: Sec. A.2.1.1. Tier 2: Sec. 5.4.1.1)</p> <p>Comments: Based on the age of construction, it is presumed detailing does not provide transfer of forces between walls and between levels of the building.</p>
C NC N/A U <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p>ADJACENT BUILDINGS: The clear distance between the building being evaluated and any adjacent building is greater than 0.25% of the height of the shorter building in low seismicity, 0.5% in moderate seismicity, and 1.5% in high seismicity. (Commentary: Sec. A.2.1.2. Tier 2: Sec. 5.4.1.2)</p> <p>Comments: Buildings to the north and south are built to or close to the property line, with minimal separation from the subject building.</p>
C NC N/A U <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	<p>MEZZANINES: Interior mezzanine levels are braced independently from the main structure or are anchored to the seismic-force-resisting elements of the main structure. (Commentary: Sec. A.2.1.3. Tier 2: Sec. 5.4.1.3)</p> <p>Comments:</p>

BUILDING SYSTEMS - BUILDING CONFIGURATION

	Description
C NC N/A U <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p>WEAK STORY: The sum of the shear strengths of the seismic-force-resisting system in any story in each direction is not less than 80% of the strength in the adjacent story above. (Commentary: Sec. A.2.2.2. Tier 2: Sec. 5.4.2.1)</p> <p>Comments: In the transverse direction (north-south), the capacity of walls in the ground and first floors is 48% and 70% of the capacity of wall in the story above, respectively.</p>
C NC N/A U <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	<p>SOFT STORY: The stiffness of the seismic-force-resisting system in any story is not less than 70% of the seismic-force-resisting system stiffness in an adjacent story above or less than 80% of the average seismic-force-resisting system stiffness of the three stories above. (Commentary: Sec. A.2.2.3. Tier 2: Sec. 5.4.2.2)</p> <p>Comments: In the transverse direction (north-south), the capacity of walls in the ground and first floors is 48% and 70% of the capacity of wall in the story above, respectively.</p>

Note: C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	San Francisco			Date:	4/8/2020		
Building CAAN:	2276	Auxiliary CAAN:		By Firm:	Estructure		
Building Name:	1326 3 rd Avenue			Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122			Page:	2	of	3

ASCE 41-17 Collapse Prevention Basic Configuration Checklist

C <input type="radio"/> NC <input checked="" type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	VERTICAL IRREGULARITIES: All vertical elements in the seismic-force-resisting system are continuous to the foundation. (Commentary: Sec. A.2.2.4. Tier 2: Sec. 5.4.2.3) Comments: Some walls are discontinuous between the ground and first story.
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	GEOMETRY: There are no changes in the net horizontal dimension of the seismic-force-resisting system of more than 30% in a story relative to adjacent stories, excluding one-story penthouses and mezzanines. (Commentary: Sec. A.2.2.5. Tier 2: Sec. 5.4.2.4) Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	MASS: There is no change in effective mass of more than 50% from one story to the next. Light roofs, penthouses, and mezzanines need not be considered. (Commentary: Sec. A.2.2.6. Tier 2: Sec. 5.4.2.5) Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	TORSION: The estimated distance between the story center of mass and the story center of rigidity is less than 20% of the building width in either plan dimension. (Commentary: Sec. A.2.2.7. Tier 2: Sec. 5.4.2.6) Comments:

MODERATE SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW SEISMICITY)

GEOLOGIC SITE HAZARD

	Description
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance do not exist in the foundation soils at depths within 50 ft (15.2m) under the building. (Commentary: Sec. A.6.1.1. Tier 2: 5.4.3.1) Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	SLOPE FAILURE: The building site is located away from potential earthquake-induced slope failures or rockfalls so that it is unaffected by such failures or is capable of accommodating any predicted movements without failure. (Commentary: Sec. A.6.1.2. Tier 2: 5.4.3.1) Comments:

Note: C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	San Francisco			Date:	4/8/2020		
Building CAAN:	2276	Auxiliary CAAN:		By Firm:	Estructure		
Building Name:	1326 3 rd Avenue			Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122			Page:	3	of	3

ASCE 41-17 Collapse Prevention Basic Configuration Checklist

MODERATE SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW SEISMICITY)

GEOLOGIC SITE HAZARD

C	NC	N/A	U	<p>SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site are not anticipated. (Commentary: Sec. A.6.1.3. Tier 2: 5.4.3.1)</p> <p>Comments:</p>
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	

HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR MODERATE SEISMICITY)

FOUNDATION CONFIGURATION

				Description
C	NC	N/A	U	<p>OVERTURNING: The ratio of the least horizontal dimension of the seismic-force-resisting system at the foundation level to the building height (base/height) is greater than $0.6S_a$. (Commentary: Sec. A.6.2.1. Tier 2: Sec. 5.4.3.3)</p> <p>Comments:</p> <p style="margin-left: 20px;">$0.6 S_a = 0.6 * 1.86 = 1.12$ Base = 25 ft; height = 35 ft Base/Height = $0.71 < 1.12$</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
C	NC	N/A	U	<p>TIES BETWEEN FOUNDATION ELEMENTS: The foundation has ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Site Class A, B, or C. (Commentary: Sec. A.6.2.2. Tier 2: Sec. 5.4.3.4)</p> <p>Comments:</p> <p style="margin-left: 20px;">Site class C.</p>
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	

Note: C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	San Francisco		Date:	1/2/2020		
Building CAAN:	2276	Auxiliary CAAN:	By Firm:	Estructure		
Building Name:	1326 3 rd Avenue		Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122		Page:	1	of	4

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W1-W1A

LOW AND MODERATE SEISMICITY														
SEISMIC-FORCE-RESISTING SYSTEM														
		Description												
C	NC	N/A	U	REDUNDANCY: The number of lines of shear walls in each principal direction is greater than or equal to 2. (Commentary: Sec. A.3.2.1.1. Tier 2: Sec. 5.5.1.1)										
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments:										
C	NC	N/A	U	SHEAR STRESS CHECK: The shear stress in the shear walls, calculated using the Quick Check procedure of Section 4.4.3.3, is less than the following values: (Commentary: Sec. A.3.2.7.1. Tier 2: Sec. 5.5.3.1.1)										
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Structural panel sheathing</td> <td>1,000 lb/ft (14.6 kN/m)</td> </tr> <tr> <td>Diagonal sheathing</td> <td>700 lb/ft (10.2 kN/m)</td> </tr> <tr> <td>Straight sheathing</td> <td>100 lb/ft (1.5 kN/m)</td> </tr> <tr> <td>All other conditions</td> <td>100 lb/ft (1.5 kN/m)</td> </tr> </table>			Structural panel sheathing	1,000 lb/ft (14.6 kN/m)	Diagonal sheathing	700 lb/ft (10.2 kN/m)	Straight sheathing	100 lb/ft (1.5 kN/m)	All other conditions	100 lb/ft (1.5 kN/m)
Structural panel sheathing	1,000 lb/ft (14.6 kN/m)													
Diagonal sheathing	700 lb/ft (10.2 kN/m)													
Straight sheathing	100 lb/ft (1.5 kN/m)													
All other conditions	100 lb/ft (1.5 kN/m)													
				Comments: Walls in the transverse and longitudinal direction of any floor do not pass the quick check stress check. At the ground floor the wall stresses in the quick check are 600 plf in the east-west direction and 2,802 plf in the north-south direction compared with the allowable 100 plf.										
C	NC	N/A	U	STUCCO (EXTERIOR PLASTER) SHEAR WALLS: Multi-story buildings do not rely on exterior stucco walls as the primary seismic-force-resisting system. (Commentary: Sec. A.3.2.7.2. Tier 2: Sec. 5.5.3.6.1)										
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: Only the second level of the west exterior wall is covered in stucco. This wall is not counted as a shear wall										
C	NC	N/A	U	GYPSUM WALLBOARD OR PLASTER SHEAR WALLS: Interior plaster or gypsum wallboard is not used for shear walls on buildings more than one story high with the exception of the uppermost level of a multi-story building. (Commentary: Sec. A.3.2.7.3. Tier 2: Sec. 5.5.3.6.1)										
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: Interior plaster or gypsum walls provide much of the shear resistance, particularly in the transverse (north-south) direction.										
C	NC	N/A	U	NARROW WOOD SHEAR WALLS: Narrow wood shear walls with an aspect ratio greater than 2-to-1 are not used to resist seismic forces. (Commentary: Sec. A.3.2.7.4. Tier 2: Sec. 5.5.3.6.1)										
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: Some of the walls considered for the quick check have an aspect ratio greater than 2 to 1.										

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	San Francisco			Date:	1/2/2020		
Building CAAN:	2276	Auxiliary CAAN:		By Firm:	Estructure		
Building Name:	1326 3 rd Avenue			Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122			Page:	2	of	4

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W1-W1A

C	NC	N/A	U	<p>WALLS CONNECTED THROUGH FLOORS: Shear walls have an interconnection between stories to transfer overturning and shear forces through the floor. (Commentary: Sec. A.3.2.7.5. Tier 2: Sec. 5.5.3.6.2)</p> <p>Comments: Existing drawings showing wall details are not provided, but it is presumed there are no ties between floors to transfer load between floors.</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
C	NC	N/A	U	<p>HILLSIDE SITE: For structures that are taller on at least one side by more than one-half story because of a sloping site, all shear walls on the downhill slope have an aspect ratio less than 1-to-1. (Commentary: Sec. A.3.2.7.6. Tier 2: Sec. 5.5.3.6.3)</p> <p>Comments: While the street in which the structure is located slopes, it does not appear the change in elevation across the transverse direction of the building is greater than one-half story.</p>
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	
C	NC	N/A	U	<p>CRIPPLE WALLS: Cripple walls below first-floor-level shear walls are braced to the foundation with wood structural panels. (Commentary: Sec. A.3.2.7.7. Tier 2: Sec. 5.5.3.6.4)</p> <p>Comments: Plywood sheathing was only observed at the rear cripple wall with unknown nailing. Based on the age of construction, available existing drawings, and site observations, cripple walls are not appreciably braced with wood structural panels.</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
C	NC	N/A	U	<p>OPENINGS: Walls with openings greater than 80% of the length are braced with wood structural panel shear walls with aspect ratios of not more than 1.5-to-1 or are supported by adjacent construction through positive ties capable of transferring the seismic forces. (Commentary: Sec. A.3.2.7.8. Tier 2: Sec. 5.5.3.6.5)</p> <p>Comments: The ground floor front wall has significant openings for the garage door. There are no wood structural panels present.</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	

CONNECTIONS

				Description
C	NC	N/A	U	<p>WOOD POSTS: There is a positive connection of wood posts to the foundation. (Commentary: Sec. A.5.3.3. Tier 2: Sec. 5.7.3.3)</p> <p>Comments: Wood posts observed did not have positive connection to the foundation.</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
C	NC	N/A	U	<p>WOOD SILLS: All wood sills are bolted to the foundation. (Commentary: Sec. A.5.3.4. Tier 2: Sec. 5.7.3.3)</p> <p>Comments: Most wood sills in the basement space were concealed by plaster. Where exposed, sills did not have any bolting. Based on the age of the building, any existing bolting elsewhere is likely not adequate.</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
C	NC	N/A	U	<p>GIRDER-COLUMN CONNECTION: There is a positive connection using plates, connection hardware, or straps between the girder and the column support. (Commentary: Sec. A.5.4.1. Tier 2: Sec. 5.7.4.1)</p> <p>Comments: Girders observed were not positively connected to columns.</p>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	San Francisco		Date:	1/2/2020		
Building CAAN:	2276	Auxiliary CAAN:	By Firm:	Estructure		
Building Name:	1326 3 rd Avenue		Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122		Page:	3	of	4

ASCE 41-17
Collapse Prevention Structural Checklist For Building Type W1-W1A

HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW AND MODERATE SEISMICITY)

CONNECTIONS						
		Description				
C	NC	N/A	U	WOOD SILL BOLTS: Sill bolts are spaced at 6 ft or less with acceptable edge and end distance provided for wood and concrete. (Commentary: Sec. A.5.3.7. Tier 2: Sec. 5.7.3.3)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: Most wood sills in the basement space were concealed by plaster. Where exposed, sills did not have any bolting. Based on the age of the building, any existing bolting elsewhere is not adequate.		
DIAPHRAGMS						
		Description				
C	NC	N/A	U	DIAPHRAGM CONTINUITY: The diaphragms are not composed of split-level floors and do not have expansion joints. (Commentary: Sec. A.4.1.1. Tier 2: Sec. 5.6.1.1)		
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: No split levels or expansion joints.		
C	NC	N/A	U	ROOF CHORD CONTINUITY: All chord elements are continuous, regardless of changes in roof elevation. (Commentary: Sec. A.4.1.3. Tier 2: Sec. 5.6.1.1)		
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	Comments: Chords are at one elevation. However, existing drawings showing splice details are not available.		
C	NC	N/A	U	STRAIGHT SHEATHING: All straight-sheathed diaphragms have aspect ratios less than 2-to-1 in the direction being considered. (Commentary: Sec. A.4.2.1. Tier 2: Sec. 5.6.2)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: Maximum Aspect Ratio = 50 ft : 25 ft.		
C	NC	N/A	U	SPANS: All wood diaphragms with spans greater than 24 ft (7.3 m) consist of wood structural panels or diagonal sheathing. (Commentary: Sec. A.4.2.2. Tier 2: Sec. 5.6.2)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: Existing drawings showing roof sheathing are not available. It is presumed the diaphragm has straight sheathing based on the age of construction. There is only one span that is greater than 24ft, which is at level 1 over the utility space.		
C	NC	N/A	U	DIAGONALLY SHEATHED AND UNBLOCKED DIAPHRAGMS: All diagonally sheathed or unblocked wood structural panel diaphragms have horizontal spans less than 40 ft (12 m) and have aspect ratios less than or equal to 4-to-1. (Commentary: Sec. A.4.2.3. Tier 2: Sec. 5.6.2)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: The diaphragm over the basement spans more than 40 ft.		

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	San Francisco			Date:	1/2/2020		
Building CAAN:	2276	Auxiliary CAAN:		By Firm:	Estructure		
Building Name:	1326 3 rd Avenue			Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122			Page:	4	of	4

ASCE 41-17
Collapse Prevention Structural Checklist For Building Type W1-W1A

C	NC	N/A	U	OTHER DIAPHRAGMS: The diaphragms do not consist of a system other than wood, metal deck, concrete, or horizontal bracing. (Commentary: Sec. A.4.7.1. Tier 2: Sec. 5.6.5)
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	
				Comments:

Appendix C

UCOP Seismic Safety policy Falling Hazards Assessment Summary

UC Campus:	San Francisco		Date:	1/2/2020		
Building CAAN:	2276	Auxiliary CAAN:	By Firm:	Estructure		
Building Name:	1326 3 rd Avenue		Initials:	AJS	Checked:	MTP
Building Address:	1326 3 rd Avenue, San Francisco, CA 94122		Page:	1	of	1

UCOP SEISMIC SAFETY POLICY Falling Hazard Assessment Summary

		Description
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Heavy ceilings, features or ornamentation above large lecture halls, auditoriums, lobbies, or other areas where large numbers of people congregate (50 ppl or more) Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Heavy masonry or stone veneer above exit ways or public access areas Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Unbraced masonry parapets, cornices, or other ornamentation above exit ways or public access areas Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Unrestrained hazardous material storage Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Masonry chimneys Comments: The facilities maintenance technician assisting with the site visit noted that the building does not have a fireplace.
P <input checked="" type="checkbox"/>	N/A <input type="checkbox"/>	Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc. Comments: The basement water heater was not anchored to the wall.
P <input type="checkbox"/>	N/A <input type="checkbox"/>	Other: Comments:
P <input type="checkbox"/>	N/A <input type="checkbox"/>	Other: Comments:
P <input type="checkbox"/>	N/A <input type="checkbox"/>	Other: Comments:

Falling Hazards Risk: *Low*

Appendix D

Quick Check Calculations

Dead loads & Seismic Weight Calculation		
Roof Assembly		
Roofing	3 psf	Estimate, Assume Asphalt Shingles
Sheathing	3 psf	Estimate, Assumed 1x Sheathing
Roof Joists	6 psf	Estimate, Assumed 2x10 @16
Ceiling	9 psf	
MEP	0.5 psf	
Misc	0.5 psf	
Walls	5 psf	
Total	Σ	27 psf

Floor Assembly		
Flooring	2 psf	Estimate, Assume Carpet
Sheathing	3 psf	Estimate, Assumed 1x Sheathing
Wood Framing	6 psf	Estimate, Assumed 2x10 @16
Ceilings	2.25 psf	Estimate, 5/8" Gyp Board
MEP	0.5 psf	
Misc	0.5 psf	
Walls	10 psf	
Total	Σ	24 psf

Exterior Wall Assembly - Wood Siding		
Finish	2 psf	Estimate, Wood Siding
Sheathing	3 psf	Estimate, Assumed 1x Sheathing
Wood Framing	1.5 psf	Estimate, Assumed 2x6 @16
Insulation	0.5 psf	Estimate, 5/8" Gyp Board
Interior Finish	2.25 psf	Estimate, 5/8" Gyp Board
MEP	0.5 psf	
Misc	0.5 psf	
Total	Σ	10 psf

Exterior Wall Finish - Stucco		
Finish	10 psf	Estimate, Stucco, less wood siding
	-2 psf	Less wood siding
Total	Σ	8 psf Add to typical ext. wall assembly, where occurs

Exterior Wall Finish - Brick Veneer		
Finish	39 psf	Estimate, Brick Veneer
	-2 psf	Less wood siding
Total	Σ	37 psf Add to typical ext. wall assembly, where occurs

Level 4 (Attic Roof)			
Roof Assembly	p	27 psf	
	A	400 ft ²	Approximate footprint
	Wt	10.80 kips	
Exterior Wall - Wood	p	10 psf	
	h _{trib}	8 ft	Approximate floor height
	L	82 ft	
	Wt	6.73 kips	
Seismic Weight	ΣW_{typ}	18 kips	

Level 3 (Attic Floor and Level 2 Roof)			
Roof Assembly	p	27 psf	
	A	850 ft ²	
	Wt	22.95 kips	
Floor Assembly	p	24 psf	
	A	400 ft ²	
	Wt	9.70 kips	
Exterior Wall - Wood	p	10 psf	
	h _{trib}	10 ft	Approximate floor height
	L	148 ft	
	Wt	15.18 kips	
Seismic Weight	ΣW_{typ}	48 kips	

Level 2			
Floor Assembly	p	24 psf	
	A	1250 ft ²	
	Wt	30.31 kips	
Exterior Wall - Wood	p	10 psf	
	h _{trib}	10 ft	Approximate floor height
	L	148 ft	
	Wt	15.18 kips	
Exterior Wall - Stucco	p	8 psf	Along front wall only
	h _{trib}	5 ft	Half approximate floor height
	L	25 ft	
	Wt	1.00 kips	
Seismic Weight	ΣW_{typ}	46 kips	

Level 1			
<i>Floor Assembly</i>	p	24 psf	
	A	1250 ft ²	
	Wt	30.31 kips	
<i>Exterior Wall - Wood</i>	p	10 psf	
	h _{trib}	10 ft	<i>Approximate floor height</i>
	L	148 ft	
	Wt	15.18 kips	
<i>Exterior Wall - Stucco</i>	p	8 psf	<i>Along front wall only</i>
	h _{trib}	5 ft	<i>Half approximate floor height</i>
	L	25 ft	
	Wt	1.00 kips	
<i>Exterior Wall - Brick</i>	p	37 psf	<i>Along front wall only</i>
	h _{trib}	5 ft	<i>Half approximate floor height</i>
	L	25 ft	
	Wt	4.63 kips	
Seismic Weight	ΣW_{typ}	51 kips	

Earthquake		Site Parameters - UCSF Group 3 Buildings – Tier 1 Geotechnical Assessment, Egan (2019)		
BSE-C	$S_s = 1.547$	$F_a = 1.2$	$S_{CS} = 1.857$	
	$S_1 = 0.61$	$F_v = 1.4$	$S_{C1} = 0.855$	

Building Period			
Empirical factor	C_t	0.02	ASCE 41-17 Sec. 4.4.2.4
Roof level height	h	35 ft	ASCE 7-18, 11.2
Empirical factor	β	0.75	ASCE 41-17 Sec. 4.4.2.4
Fundamental period, $T = C_t h_n^\beta =$		0.288 sec	ASCE 41-17 Sec. 4.4.2.4 eqn. 4-4

Calculate Base Shear			
Spectral Acceleration	$S_a = S_{X1} / T = 2.97$		ASCE 41-17, 4.4.2.3
	$S_{a,max} = S_{XS} = 1.85688$	<i>governs</i>	ASCE 41-17, 4.4.2.3
Modification Factor	$C = 1.00$		ASCE 41-17, Table 4-7
Pseudo Seismic Force	$V = S_a \times C \times W =$	$1.86 \times W$	ASCE 41-17, Eqn. 4-1
	V =	303 kips	

Seismic Force Vertical Distribution						
Level	Weight (kips)	Height (ft)	$w_x h_x$ (kip_ft)	$C_{vx} = w_x h_x / \sum w_x h_x$	$F_x = C_{vx} V$	Story Shear, V
Attic	18	35	613	0.17	52	52
3rd	48	31	1483	0.42	126	178
2nd	46	20.5	953	0.27	81	259
1st	51	10	511	0.14	43	303
		0	0	0.00	0	303
Σ	163	Σ	3560	1.00	303	

Longitudinal Direction (East-West)							
Story	Story Shear (kips)	Length of Wall (ft)	M _s Factor (ASCE 41-17, Table 4-8)	Average Story Shear Stress (plf)	Quick Check Shear Capacity ⁽¹⁾ (plf)	Pass? (Y/N)	Lvl N Strength / Lvl N+1 Strength
3	52	49	4.5	236	200	N	--
2	178	170	4.5	233	200	N	347%
1	259	140	4.5	411	200	N	82%
Ground	303	112	4.5	600	200	N	80%

Transverse Direction (North-South)							
Story	Story Shear (kips)	Length of Wall (ft)	M _s Factor (ASCE 41-17, Table 4-8)	Average Story Shear Stress (plf)	Quick Check Shear Capacity ⁽¹⁾ (plf)	Pass? (Y/N)	Lvl N Strength / Lvl N+1 Strength
3	52	30	4.5	386	200	N	--
2	178	71	4.5	558	200	N	237%
1	259	50	4.5	1152	200	N	70%
Ground	303	24	4.5	2802	200	N	48%

1. Shear capacity is doubled where walls are covered on both sides.